


Engineering Metrology
Prof. J. Ramkumar
Dr. Amandeep Singh Oberoi
Department of Mechanical Engineering & Design Programme
Department of Industrial & Production Engineering
Indian Institute of Technology, Kanpur
National Institute of Technology, Jalandhar

Lecture - 11
Laboratory demonstration: Vernier Caliper


Welcome back to the course on Engineering Metrology. This is the special session wherein we will study the instruments will do the practical measurements using the instruments that we have learned or that we have studied in those theoretical part. The first instrument I will select here is Vernier Calliper.

(Refer Slide Time: 00:32)




So, these are the two vernier calipers that we will discuss. These are both manufactured by Mitutoyo Japan and they has certain specifications, you can see the instrument here, it has various components.

(Refer Slide Time: 00:49).



This instrument is having main scale. The length of the main scale of the instrument is about 12 inches. You can see that it is calibrated up to 200 mm on the main scale on the lower side.

(Refer Slide Time: 01:05).



It is actually 200 mm; however, the length of the scale is even larger. Actually this length is to accommodate the other scale or the other part that is, the moveable part of the caliper, moveable part of the instrument that we will just discuss and on the upper side of the scale of the main scale we have in scale which is calibrated up to 8 inches.

However, the certain other calibration lines that you can see here. So, the material of this specific vernier caliper is stainless steel, stainless hardened steel. So, it has various components as we have discussed in the theory as well, the first component is the solid L shaped frame, the solid L shaped frame and we have which is actually fixed, it has two cat type calipers on the both sides and another is caliper that is moveable.

You can see the solid frame here, we in which are two calipers on the both sides. Actually, they are two jaws, the jaws on the lower side is for the external dia. We can measure the external diameter of the cylinders, spheres of any body that we require using the lower jaws and the upper jaws which can be inserted into the cylinder that can be used to measure the internal dia.

See if we close it completely you can see the external jaws are also closed and internal jaws are also closed and when we open it a little, you can see this internal jaws which are on the upper side, they can be inserted inside and the external jaws are can be can hold the work piece from the outside.

We can very well see the whatever the length, whatever is the slot length or whatever is the gap between the lower jaws, that you can see the space is equivalent to the lengths between or the distance between the upper jaws. So, the main scale is graduated in millimeters on the lower side and inches on the upper side. There is another scale which is the critical component of this vernier caliper that is known as vernier scale.

You can see the markings from 0 to 10, the numbers are written from 0 to 10 which is a vernier scale and within 1 within this 1 division, not 1 division within this 1 number from 0 to 1, we have 5 divisions; from 1 to 2 we will have 5 divisions. So, this makes from 0 to 10, it is 10 into 5; it is equal to 50 divisions. Also you can see the least amount is written here 0.02 mm, least count is written here.

So, it has a screws attached to it, this is actually on the lower side we have the fine adjustments screw and on the upper side we have the clamping screws. How do we operate this one? First, we tight the screw which is on the right hand side; first we tight this screw this is on the right hand side and then using the fine adjustment screw, we can adjust the distance of the vernier scale.


Then the vernier caliper is as I have said is made up of either stainless steel or tool steel depending upon the nature and severity of the applications. So, it has grade, graduations which can be either in forward vernier or backward vernier. This specific vernier caliper that we have in hand is the forward vernier. You can see that reading first starts from 0 to 10, had it been from 10 to 0 it might be called as on the vernier scale on the very had it been from 10 to 0 it might be called as a backward vernier.

So, as the clamping screw enables the caliper of the movable jaw in a particular position after the jaws have been set accurately over the jaw being measured. Now, this adjusts the further motion of the moveable jaw. The moveable jaw when it is locked using the clamping screw, the operator now note on the reading in a convenient position because the jaws will not move further. Now, the finer adjustment screws enables the operator to accurately enclose the portion of the jaw where measurement is required by applying optimum clamping pressure. However, there are certain guidelines before using the vernier caliper I would like to tell them.

We need to clean the equipment, clean the vernier caliper or any equipment. This is the basic precaution or guideline that we use in a instrument. This vernier caliper is actually the analog or mechanical vernier caliper. We also have a digital vernier calipers, where we can adjust the 0. At any position we can say this is the 0 position, the 0 can be adjusted because that had digital scale, but in this vernier caliper we need to calculate this zero error if it is there and the deterioration happens due to small dust particles or the tiny chips which can clot or which can come in between the rack and pinion arrangement of the vernier caliper that can hinder it.

So, it is important to clean it properly. So, the first part is I have to clean the jaws from this part because you know it is calibrated based upon this surface. So, this is a flat surface the flatness has to be up to 0 level like approximately 0 levels; however, there is no 0 actual 0 level that exists. So, it has asked to be cleaned from here; however, we can use the cotton to clean it using acetone. So, let us first clean the instrument and the work piece.

(Refer Slide Time: 07:46).



So, now I have this cylinder, for which I like to see the internal dia, the external dia and also we have the height or what we can call it width, I like to see this dimensions. Before that while we are cleaning it, I like to just tell the guidelines. When the calipers jaws are fully closed, it should indicate 0, if it does not it must be recalculated or repaired.

Now, loosely the clamping screw and sliding the moveable jaw altering the opening between the jaw is slightly more than the feature to be measured. So, let us clean first. So, the work piece is to be cleaned now. So, we have applied a little acetone here. So, I like to first see the external dia, also not to forget, if we see the back side of the vernier caliper, you can see there is a straight probe; this is this can also be known as depth gauge.

(Refer Slide Time: 09:30).



If we open it, if we open it we can also see the depth you can see. This is a probe, this is a scale, if you open it whatever the length it is getting opened that is the length that length can also be read on the vernier scale.

So, I will first explain the vernier principle, the principle of the vernier caliper.

(Refer Slide Time: 09:55).



Actually vernier caliper was invented in 1631 by Pierre Vernier, who was a scientist and this is the instrument which is I can say most widely used in the industry. There are certain measurements that we can just do using the scale, the main the general steel rule.

But the steel rule will do a least steel rule generally 1 mm or might be it sometimes it is 0.5 mm; 1 mm is divided into two parts. But the vernier caliper points up to 0.1 mm of a least count is available, least count is nothing least count is a minimum reading that can be read that can be taken using the specific instrument.

So, before checking the reading I like to discuss the principle of vernier caliper. So, you can see that there are 50 divisions on the vernier scale. See, if you see the numbers, the numbers are from 0 to 10; between 0 to 1 there are 5 divisions, between 1 to 2 there are 5 divisions, between 2 to 3 there are 5 divisions. If I continue this thing, it is 5 divisions into 10 times; it becomes 50. So, the 50th division of the vernier scale, the lower scale that is a vernier scale is matching with some reading on the main scale if you can see.

So, you can see that the last reading of the vernier scale is coinciding with the reading which reading? Which reading of the main scale? 49th, if you see the numbers between 40 and 50 the divisions between 40 and 50 on the main scale. It is from the one reading ahead of the 50, it is the 49th reading. The last reading on the vernier scale is coinciding with the 49th reading of the main scale. If this coincidence is there this means that the 0 is perfect, there is no zero error. So, this is actually 49 to 50, I will like to explain this principle by using a most simple calculation.

(Refer Slide Time: 12:18)

Vernier Calliper
Principle of Vernier Caliper

$10 \text{ div. of VS} = 9 \text{ divisions of MS}$
 $10(\text{VS}) = 9(\text{MS})$
 $\text{VS} = \frac{9}{10} \text{ MS}$
 $= 0.9 \text{ MS}$
 $1 \text{ V.S.D} = 0.9 \text{ M.S.D}$
 $= 0.9 \text{ mm}$

$\text{VS} = \frac{49}{50} \text{ MS}$
 $1 \text{ V.S.D} = 0.98 \text{ M.S.D}$
 $= 0.98 \text{ mm}$


So, let me say there is a scale in which we have 9 divisions 0, 1, 2, 3, 4, 5, 6, 7, 8 and 9; these 9 divisions I will call it main scale, 1, 2 and 9 and there is another scale which has

10 divisions; 1, 2, 3, 4, 5, 6, 7, 8, 9 and 10, I think let us call it this is principle of vernier caliper.

So, what is happening? This 10 divisions of vernier scale, 10 divisions of the vernier scale I will call it VS is equal to 9 divisions of main scale, which implies 10 into vernier scale is equal to 9 into main scale, which implies vernier scale is equal to 9 by 10 of main scale is equal to 0.9. That means, vernier scale is equal to 0.9 times of main scale; that means, 1 Vernier Scale Division is equal to 0.9 Main Scale Division or this is equal to 0.9 mm.

What if this number is 49 here and this number is 50 here in the present scale? That implies vernier scale is equal to 49 by 50 of main scale; that means, 1 vernier scale division is equal to it is about it is 0.98 main scale divisions is equal to 0.98 mm. So, what does this gets us to?

(Refer Slide Time: 15:42)



This implies that if I see the first division, if this is the main scale, if this is the main scale and this is our vernier scale below, if this is 1 mm, this first division and this value we can say one vernier scale division is equal to 0.98 mm, which means this value is 0.98 and this value is equal to 0 point or I can better call it better calculate it in a way 1.0 total 1 minus 0.98 is equal to 0.02 mm. That is the first reading is 0.02 mm.

Now if the first reading is 0.02 mm what will be the second reading? It could be 0.04, 0.06, 0.08, so on up to 0.02 into 50 that is equal to 1 mm.

So, these are the divisions which our vernier scale has. So, when we see that which point is coinciding when, we have to need to see the point that is coinciding that gives us that how many divisions ahead of the main scale division of a vernier scale is, we will just do certain measurements here and that will make it more clear. Also here, we need to adjust for this 0. Now this gives because this is the least count.

So, I can say that in general n vernier scale divisions is equal to $n - 1$ main scale divisions which means 1 vernier scale division is equal to $n - 1$ by n main scale division, this gives us the least count; that means, least count is equal to 1 main scale division minus 1 vernier scale division. This is known as the least count, which is equal to 1 main scale division minus $n - 1$ by n vernier scale divisions which is equal to actually $1/n$ of the main scale divisions.

So, this is our least count, the formula for the least count in general. So, let us try to see the dia of the cylinder that we have, let us first try to see the external dia. Now we will see the external dia of this cylinder, one thing is that we can just use the main scale just using the steel rule to see the measure dia, but the accuracy or the least count they would be 1 mm. Let us see up to the second place of decimal and only the even numbers that is 0.02 least count what is the dia external dia of this?

See we are using, here we using the finger lock to see. First will lock the clamp in which we are just moving screw then we will then we have then we will use the fine adjustments screw to provide to put the pressure. So, what is the way to do? It is when we loosen the clamping screw and slide the moveable jaw, altering the opening between the jaw slightly more than the feature to be measured.

Here the feature that is to be measured is the cylinder, we open it little more than that and hold the feature in the jaws, then place the fixed jaw in contact with the reference point. This is the way actually we open it a little more than the feature to be measured, then place the feature that is surrender to the fixed jaw. It is placed in a fixed jaw. Now, the moveable jaw is taken close. Now, we will lock we clamp the screw, now using fine adjustment screw, we can apply a little pressure. Now we tighten the clamp screw on the

moveable jaw without disturbing the light contact between caliber in the jaw, then we will tighten the screw.

Then we will remove the feature. Then will remove the feature, now because both the screws both the clamping screws are locked we can very conveniently see the readings. Now to see the readings, let us see what is the 0? 0 of the vernier scale is matching with 51, 50 is actually not matching is a little forward then the 51st division. That is it is about 51 and we will see which reading is coinciding. So, let us see which reading is coinciding, actually this is a close look we have to be careful. The best coincidence here is the reading number 4 between 0 to 1, the 4th reading is coinciding, which means the dia of this work piece is equal to main scale reading, main scale reading plus least count into the coinciding vernier scale reading.

(Refer Slide Time: 22:16)

Vernier Calliper

Observation 1.

$$\begin{aligned} &= \text{M.S.R.} + \text{L.C.} \times \text{V.S.R.} \\ &= 51 + 0.02 (4) \\ &= 51.08 \text{ mm} \end{aligned}$$

Observation 2.

$$\begin{aligned} &= \text{M.S.R.} + \text{L.C.} \times \text{V.S.R.} \\ &= 51 + 0.02 (9) \\ &= 51 + 0.18 \\ &= 51.18 \end{aligned}$$

[0.10 mm]

$$\frac{51.08 + 51.18}{2} = 51.13 \text{ mm}$$

So, which is equal to main scale reading is 51 plus least count is 0.02 into 4th reading which is equal to 51.08 mm, this is the external dia. So, actually when we do the calculations when we do the measurements, it is not done only one, as we will discuss statistical aspects of metrology no reading is taken only once. Generally, we do not trust the single measurements we do multiple measurements.

So, we will check the dia at some other location as well. Again the same procedure; opening, moving it to the fixed jaw, then closing, locking, the clamp, locking, then fine adjustment screw, a little pressure so that we can do the properly. Now, let us see the

readings again. So it is about 51, main scale readings are again 51; this is observation 1, then observation 2. The main scale reading here is 51 plus least count into vernier scale reading. Let us see which vernier scale reading is coinciding. If you see it closely the reading that is coinciding here the 9th reading is coinciding.

So, it is 9th reading which is equal to 51 plus 0.18 is equal to 51.18. So, you can see that two observations, the two observations there is a difference of 0.1 mm. So, when we see it by using generally a scale, the reading would be the reading at we when we that we can see is just I think it would be 51 only. The dia actually it has to touch a reference plane here, [FL] the dia is about, the dia is about 51. So, the thing is that this difference 0.08, 0.18, so, we can do multiple observations using this and take an average.

So, that average will send the next reading if it comes 51 point; if I take only these two readings as my final observations, the final dia of this work piece would be 51.8 plus 18 is 51.13. So, it is because like this 51.08 plus 51.18 by 2 average is equal to 51.13 mm. So, why is this that different this work piece can we see why this difference this error is there? If we see this work piece closely you can see that on the external portion we have this serrations here, this is actually knurling that is done here.


(Refer Slide Time: 26:07)



Because of this knurling, so, there are ups and downs, there are tress and trough, there are peaks and valleys there because of this at different locations the dia coming a little different. So, this is quite sensitive to our vernier caliper. Vernier caliper which is having

least count or sensitivity equal to 0.02 mm that is able to identify this difference. So, this difference is high, this is event is out of the order of based on these divisions this difference is of the order of 0.1 mm that I have just written here. So, also we can see the internal dia. So, I will pick another work piece here for which I will use all the jaws the depth gauge, the internal external to draw the full drawing of to draw to identify or to see the full measurements or full dimensions of this work piece.


(Refer Slide Time: 27:03).



So, I can see you know now this work piece has waste portions, it has a small cylinder, it has a big cylinder, you have a slot in between ok, then we have a small hole on the upper side basically, this is the through hole and also we have a thread hole a keyhole that is also thread there internals thread here. Let us see all this dimension. Could I draw drawing of this could I draw the specifications or could I get this specification in a mixed drawing of this component? Let us see.

So, it is this kind of component I will make it drawing while we will see the dimensions. Let us see the external dia of the bigger circle. So, this dia using same procedure the reading that is coinciding, I will just note down the reading then would not show the calculations, directly will be saving time this way.

(Refer Slide Time: 28:15).



So, the single dia here is in the vernier caliper, the approximate reading here is.

Student: 49 units per.

It is this dia, let me call it capital D let me choose some different colour before dimensioning, it is 49; I will just use main scale division plus 0.02 into vernier scale division; it is 49 plus 0.02.

Student: 11.


Into 11; you can see the 11th reading is coinciding here. So, this is 49 into sorry 49 plus 0.22 is equal to 49.22, I will just put this value here. Next is the internal dia, this is small d, this is capital d, this is let me call it capital T, let me call it small t, let me call this depth, we can see the internal dia as well by inserting the internal jaws inside the cylinder, you are locking the screws using the same principle, after locking the screws we can see the reading. So, the internal dia is the main scale reading is 11 and the coinciding point is 44th, it is 11 plus 0.2 into 44. This is small a, this is equal to 11.44 mm. So, up to two places of decimals and even numbers we can see all these dimensions.

So, this dimensions small d is there then this small t, capital T, and t dash, also we can see this small dia, let me call it s. So, we will put all this calculations and word you with the notes. So, this was actually the purpose of this demonstration was to show the show this principle and use of the vernier caliper. This vernier caliper, the vernier scale is not

only used in the calipers, it can also be used in height gauge. Height gauge is also one of the instruments that we will use for the demonstrations for the.

Now, there are certain precautions when we use the caliper; some general precautions and some specific to this vernier caliper.

(Refer Slide Time: 32:04).



The first precaution I would put is the measuring force, do not apply excessive force to the work piece, excessive measuring force we develop measurement errors because of the positions deviations of jaws. So, no excessive force, it can lead to positional deviation errors. Number 2 is the observer error that is parallax error; however, the instrument is quite clear, the we can see which reading is coinciding which of the vernier scale readings coinciding with the main scale, but in general parallax error could also come; not in vernier caliper in general parallax error is avoided, this is it is instrumented is not that sensitive that parallax error would be significant here, but it is an important, error if it comes it can give us difference over 1 reading at least.

So, number 3 is the outside measurement; the outside measurement we can put the work piece as close to the reference surface as possible and have the measuring phases fitted with the work piece because the outside measurement sometimes if it is not put in a proper way it can give us some error then inside measurement also has similar kind of drawbacks may have similar kind of drawbacks inside measurements.

So, inside measurements or in outside measurements it is important to note the maximum reading and the smallest reading; maximum and you call it minimum. Take both readings at least if possible then also I did not use that depth measurement, I can also use the depth gauge. In depth measurement, you can see the depth of this work piece using the depth gauge.

(Refer Slide Time: 34:52)



For using that depth gauge, I have we need a flat surface we are actually not using the surface plate. So, I have put picked this spirit level, spirit level is also smoothened, it is grounded properly. If the ground is 1 by 10000th of edge this much sensitivity this much smooth surface is there. So, we have inserted the depth gauge in this, made it to touch the base, now we can note the reading. Now while using the depth instrument or the depth measurement there are certain precautions like set the depth for perpendicular to the measured surfaces, also we can do some step measurement. In step measurement what happens? We have the step measuring phase fitted with the major surfaces. The step measurement can be like we have groove, we have a groove in the work piece. This can also be called as the step.

So, we have a groove here, we step down here then we come up; actually this is this dia same and this is a step. So, in step measurement it has to be closed then positional error could also come you have to be careful about that. So, for the depth measurement main scale readings 41 and the vernier scale reading is it is actually $T + t$; this is total here,

this is 41 plus 0 point it is 0.02, 0.02 into 7; 7th reading is coinciding; it is equal to 41.44 mm. So, this is our vernier calipers, we also have another vernier caliper. Actually in this vernier caliper also we did not have any zero error. Had it been a zero error we have to add or subtract that sometimes the 0 is not coinciding, sometimes a reading is forward or backward.

So, some it is not coinciding. So, we have to adjust it accordingly. So, whenever it is forward, it would mean that the reading is a little larger whether it of the detective jaws which are closed when the jaws are open in little this is known as positive error. So, whatever reading that we gather is sense if I get reading 50.20, if this error is 0.10, so, this 50.20 is 0.10 is something that is added to it when you need to subtract that; this positive error has to be subtracted and if it is an overlap, if it is an overlap that will be a negative error that has to be added. So, we have to adjust it for the errors. To give with the errors, so, as the zero error does not occur, the instrument error we have the dial gauge, we have the dial vernier. The dial vernier is the one first I will discussed the dial gauge then I will discuss dial vernier, after that and also there as I said they are digital vernier calipers in which we can set 0 at any point, so that can also be the deal with the zero error.

So, this was the vernier caliper. In the next part of lab demonstration, I will discuss about the dial gauge and the dial vernier. Then we will move to the micrometer. Let us meet in the next part of the lab demonstration.

Thank you.